



## Case Study

### Drain Pipe Repair

**Crawford Division:**

Plumbing

**Client:**

Fazoli's Restaurant

**Challenge:**

Under slab drain pipe repair, while keeping restaurant open for business

**Solution:**

Locate and repair broken drain pipe, installation of new piping, concrete replacement, cabinet replacement



**Project Summary:**

Crawford Company's Plumbing Division responded to a call for service at Fazoli's Restaurant. Crawford found broken drain piping under slab. The piping was located with Crawford's sewer camera device.

Crawford's team coordinated with Fazoli's to replace piping while the restaurant stayed open for business. The job included: removal of soda machine island cabinets, saw cutting of the concrete inside and outside, installation of new waste piping, replacement of concrete, and building and installing new soda cabinets. Crawford also arranged to isolate work areas from dining room, lessening the impact on customers.

